Manitowoc
ICE MACHINES & REACH-INS

K00132

I-25/45 LEG BRACKET KIT

Installation Instructions

1. Disconnect power and water to ice machine. Drain water and empty ice from bin.
2. Tilt ice machine at 45° angle and brace up to hold in place. CAUTION: Placing ice machine on its side (greater than 45° angle) can cause compressor failure.
3. Hold a leg bracket 11/16" (1.75 cm.) from front of metal base and even from side to side with metal base. Mark and drill four 5/32" (.37 cm.) diameter holes in base at the mounting hole locations in leg bracket. Repeat these steps for the other leg bracket, but locating dimension will be from back of metal base.
4. Attach leg brackets with screws (supplied) at the drilled holes.
5. Screw legs into new leg brackets. NOTE: Legs ordered separately.

Leg Length	Part Number
4 3/8"	K00043001 (set of four)
6"	K00020000 (set of four)
12"	K00040000 (set of four)

Place ice machine upright and connect water and power.

Manitowoc Ice, Inc.
2110 South 26 Street, P.O. Box 1720, Manitowoc, WI 54221-1720 USA
Telephone 920-682-0161, Fax - Sales: 920-683-7589, Service/Parts: 920-683-7585, Other: 920-683-7879
8009933
Rev. 08/19/97