MANITOWOC ICE
2110 SOUTH 26TH STREET, MANITOWOC, WI 54220
800-545-5720
WWW.MANITOWOCICE.COM

Service Bulletin

Subject: Indigo Control Board

INDIGO REPLACEMENT CONTROL BOARD 000008309

⚠Warning

Authorized Service Representatives are obligated to follow industry standard safety procedures, including, but not limited to, local/national regulations for disconnection / lock out / tag out procedures for all utilities including electric, gas, water and steam.

⚠DANGER

Disconnect electric power to the ice machine at the electric switch box before proceeding. Failure to disconnect the power at the main power supply disconnect could result in serious injury or death. The power switch DOES NOT disconnect all incoming power.

Indigo Control Board Relays

An operational issue has been identified with the relays on the Indigo control board. The relays can operate erratically, by not closing the relay contacts when the relay coil is energized. Indication would be an energized relay light on the control board and line voltage is not present at the corresponding 9 pin molex connector. An improved relay is currently being used in all Indigo control boards.

If relay issues are experienced on an Indigo model control board, replace the control board with part number 000008309 using the standard warranty procedure.

NOTE: Control board part number 000008309 with a replacement part date of March 31st 2017 (3/31/17) or later have the improved relays.

Indigo Control Board Schematic

