
S850/S1000/S1200 Remote 3 ph



* - COMPRESSOR HAS INTERNAL OVERLOAD

* * - SOME AIR COOLED MODELS MAY NOT HAVE RUN CAPACITOR ON FAN MOTOR