7621923
MERCURY RELAY KIT

INSTRUCTIONS FOR MDB-290 DISPENSER

INSTRUCTIONS FOR REPLACING CONTACTORS, 2410143 AND 2410153, WITH A MERCURY RELAY.

ASSEMBLY CONSISTS OF:
- (1) MERCURY RELAY, 2410193
- (4) 1/4 X 6-32 RECEPTACLES, 2510503
- (2) #6-32 MACHINE SCREWS
- (1) 1/4 COMBINATION RECEPTACLE, 2510383
- (1) INSTRUCTION SHEET, 8002113

INSTRUCTIONS:

1. Disconnect electrical power.

2. Disconnect all wire leads from and remove existing contactor.

3. Drill one hole, .136 dia., for mounting mercury relay 5/8" to the right of the existing bottom left-hand hole used to mount the contactor.

NOTE: On an MDB-290 with a serial number before 82015260, see back side for relay mounting.

4. Mount mercury relay using the screws from the contactor mounting.

5. Attach the 1/4" female receptacles and rewire, as shown.

NOTE: On an MDB-290 with push-button ice and water, attach the enclosed 1/4" male/female combination receptacle to one of the two #11 wires.

MERCURY RELAY MOUNTING ON AN MDB-290 WITH A SERIAL NUMBER BEFORE 82015260

7621923
MERCURY RELAY KIT

INSTRUCTIONS FOR
CSA-151 DISPENSER

ASSEMBLY CONSISTS OF:
(1) MERCURY RELAY, 2410193
(4) 1/4 X 6-32 RECEPTACLES, 2510503
(1) INSTRUCTION SHEET, 8002113

INSTRUCTIONS:

1. Disconnect electrical power.

2. Disconnect all wire leads from and remove existing relay.

3. Mount relay using existing screws. Mounting holes are provided.

4. If the relay you are replacing has eyelet lead wire connections, use the four 1/4 x 6-32 receptacles supplied.