MANITOWOC ICE
2110 SOUTH 26TH STREET, MANITOWOC, WI 54220
800-545-5720
WWW.MANITOWOCICE.COM

Instruction Sheet

Subject: Receiver Service Valve With Cap

REFRIGERANT LEAK PREVENTION

Important
To prevent refrigerant leakage: • Verify the valve stem is fully backseated • Install the valve cap • Tighten the valve cap with a wrench