DANFOSS COMPRESSOR

Installation Instructions

THE SUPPLIED 56% SOLDER WITH FLUX CORE IS REQUIRED
FOR BRAZING TUBING TO COMPRESSOR

FOLLOW STANDARD BRAZING PROCEDURES
DO NOT USE ADDITIONAL FLUX
DO NOT USE SOLDER WITH LESS THAN 56 % SILVER CONTENT

Manitowoc Ice, Inc.
2110 South 26 Street, P.O. Box 1720, Manitowoc, WI 54221-1720 USA
Telephone 920-682-0161, Fax - Sales: 920-683-7589, Service/Parts: 920-683-7585, Other: 920-683-7879
Web Site - www.manitowocice.com

8013953
09/10/02