
RELAY REPLACEMENT INSTRUCTIONS

1. The Electrica relay will not function properly unless it is mounted in the correct orientation. Refer to label affixed to relay.

2. Insulated wire terminals will not fit properly on Electrica relay.

3. Wire harnesses with insulated terminals can only be used in conjunction with the non-insulated duplex ("piggyback") terminal provided.

Correct Orientation



Manitowoc Ice, Inc.
2110 South 26th Street, P.O. Box 1720, Manitowoc, WI 54221-1720 USA

Telephone 920-682-0161, Fax - Sales: 920-683-7589, Service/Parts: 920-683-7585, Other: 920-683-7879
Web Site - www.manitowocice.com
8014483
07/29/03