
FOAM TAPE

Installation Instructions for Marine Ice Machines

This ice machine must be installed per CDC construction guidelines of the Vessel Sanitation Program, Section 8.0 - Equipment Placement and Mounting.

Foam Tape Installation:

1. Remove front panel.
2. Apply tape to bracket, as shown.
3. Replace front panel.



Manitowoc Ice, Inc.
2110 South 26th Street, P.O. Box 1720, Manitowoc, WI 54221-1720 USA
Telephone 920-682-0161, Fax - Sales: 920-683-7589, Service/Parts: 920-683-7585, Other: 920-683-7879
Web Site - www.manitowocice.com

8015333
Rev. 06/15/04