MANITOWOC ICE
2110 SOUTH 26TH STREET, MANITOWOC, WI 54220
800-545-5720
WWW.MANITOWOCICE.COM

Instruction Sheet

Subject: K00489 - Coke Freestyle Riser

INSTALLATION INSTRUCTIONS

⚠Warning

Authorized Service Representatives are obligated to follow industry standard safety procedures, including, but not limited to, local/national regulations for disconnection / lock out / tag out procedures for all utilities including electric, gas, water and steam.


DANGER

Disconnect electric power to the ice machine at the electric switch box before proceeding. Failure to disconnect the power at the main power supply disconnect could result in serious injury or death. The power switch DOES NOT disconnect all incoming power.


⚠Warning

This equipment contains refrigerant charge. Procedures must be performed by a properly trained and certified refrigeration technician aware of the dangers of dealing with refrigerant charged equipment.


1. Place riser on adapter and position as shown.



2. Attach retention straps to the adapter and mark position on the riser.



3. Drill two 5/32” holes through one wall of the riser tubing. Do not drill through both walls of the riser.
4. Secure the riser to the adapter with the two supplied screws.



Document Number: 000016122 Rev00 9/19