MANITOWOC ICE
2110 SOUTH 26TH STREET, MANITOWOC, WI 54220
800-545-5720
WWW.MANITOWOCICE.COM

Service Bulletin

Subject: CVDF & CVDT Delay Timer Temporary Bypass

SYMPTOM:

Delay timer does not supply voltage to the contactor after the five minute delay or contactor is chattering (low voltage).

⚠Warning

Authorized Service Representatives are obligated to follow industry standard safety procedures, including, but not limited to, local/national regulations for disconnection / lock out / tag out procedures for all utilities including electric, gas, water and steam.

DANGER

Disconnect electric power to the ice machine and condensing unit at the electric switch box before proceeding. Failure to disconnect the power at the main power supply disconnect could result in serious injury or death. The power switch DOES NOT disconnect all incoming power.

TEMPORARY BYPASS

1. Disconnect power to the condensing unit.
2. Follow lock out tag out procedures.
3. Inspect contacts on contactor for any pitting/scoring, replace contactor if pitting/scoring is visible.
4. Disconnect blue wire from timer, and place on contactor coil next to the yellow wire.
5. Re-apply power to condensing unit.

NOTE: The delay timer is non-replaceable. Please order a delay timer removal kit 000018012 from your local distributor.



