

I-SERIES ICE MACHINES
REMOTE 1 PHASE
CAUTION: DISCONNECT POWER BEFORE WORKING ON ELECTRICAL CIRCUITRY.




000008864
REV. 00